

SECRET

PRIORITY

OUT54475

1964 NOV 17 23 30Z

P 172145Z *Multi*  
 FM NPIC WASHDC  
 TO RUCSC/SAC OFFUTT AFB OMAHA NEB  
 RUCVAA/4080 STRAT WG OL 19 BARKSDALE AFB LA  
 RUCVAA/2D RTS BARKSDALE AFB LA  
 RUEAHQ/DIA WASHDC  
 RUECYH/NAVRECONTECHSUPPCEN SUITLAND MD  
 RUEPIA/CIA WASHDC  
 RUWBKN/15TH AF MARCH AFB RIVERSIDE CALIF  
 RUWGAA/2AF BARKSDALE AFB LA  
 BT  
 S E C R E T CITE NPIC 3305.

138-117-104

HFS

WCB

GPC

PNS

ACT

TOPS FILES-

15TH AF (FOR DI), SAC (FOR DIM/GOLDEN TREE/DOCR, DM 4) 2D AF (FOR DI).

1. CAMERA B 101 WAS USED IN MISSION 3967 FLOWN ON 16 NOVEMBER 1964. PROCESSING WAS ACCOMPLISHED BY BARKSDALE.

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.


B. 9R SIDE: INBOARD ROLLER CHATTER IS CONTINUOUS ON THE FIRST 10 PERCENT OF THE MISSION. THERE IS A MANUFACTURING SPLICE ON FRAME 1171. THERE IS AN OBSTRUCTION IN THE DATA CHAMBER OF EACH FRAME WHICH OBLITERATES A PORTION OF THE FLIGHT DIRECTION ARROWS.

C. 9L SIDE: MINOR ROLLER CHATTER IS PRESENT ALONG THE INBOARD AND OUTBOARD EDGE OF THE FIRST 30 FRAMES. A PLUS DENSITY AREA APPEARS NEXT TO THE CLOCK THROUGHOUT THE MISSION. THERE IS AN UNDEVELOPED AREA 0.45" LONG ON FRAME 1082, 1.5" FROM THE INBOARD EDGE. A MANUFACTURING SPLICE APPEARS ON FRAME 1121.

D. BOTH SIDES: INBOARD AND OUTBOARD EDGE FOG IS PRESENT THROUGHOUT THE MISSION. INBOARD AND OUTBOARD EDGE STATIC OCCURS

Declassification Review by NGA/DoD

SECRET



DURING THE FIRST THIRD OF THE MISSION. THE LAST TITLED FRAME IS  
2167.

E. THERE WERE NO MAJOR CAMERA OR PROCESSING MALFUNCTIONS.

3. POSITIVE:

A. THE PI SUITABILITY IS GOOD.

B. THE PRINTING AND PROCESSING WAS GOOD.

C. CLOUDS DEGRADED OR OBSCURED 15 PERCENT OF THE MISSION.

GP-1

S E C R E T

--END OF MESSAGE--